

Report No.: EED32P80600802




Page 36 of 38


8 PHOTOGRAPHS OF TEST SETUP

(

Test Model No.: DR001



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32P80600802









Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



AC Power Line Conducted Emission















Report No.: EED32P80600802



9 PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No.: EED32P80600801 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.





