


Report No. : EED32N80955402 Page 43 of 45

9 PHOTOGRAPHS OF TEST SETUP

Test Model No.: vimbod hub1



Radiated spurious emission Test Setup-1(Below 1GHz)




Radiated spurious emission Test Setup-2(Above 1GHz)



Page 44 of 45 Report No.: EED32N80955402



Radiated spurious emission Test Setup-5(Above 1GHz)
There are absorbing materials under the ground.



AC Power Line Conducted Emission















10 PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No.EED32N80955401 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

*** End of Report ***

