


Report No. : EED32N81477101 Page 34 of 43

7 PHOTOGRAPHS OF TEST SETUP





Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(1-18 GHz)



Report No. : EED32N81477101 Page 35 of 43



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



Conducted Emissions Test Setup-4