


Report No. :EED32O80246801 Page 22 of 31

## PHOTOGRAPHS OF TEST SETUP

Test model No.:D100BL



Radiated spurious emission Test Setup-1(Below 1GHz)




Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32O80246801





Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



**AC Power Line Conducted Emission Test Setup** 









