

Report No. : EED32O80248501




Page 28 of 34

9 PHOTOGRAPHS OF TEST SETUP

Test model No.:CV235



Radiated spurious emission Test Setup-1(Below 1GHz)



Hotline:400-6788-333 www.cti-cert.com E-mail:info@cti-cert.com Complaint call:0755-33681700 Complaint E-mail:complaint@cti-cert.com