


Report No.: EED32O81225001 Page 22 of 34

APPENDIX 1 PHOTOGRAPHS OF TEST SETUP

Test Model No.: D0-315



Radiated emission Test Setup-1(9kHz~30MHz)



Radiated emission Test Setup-2(9kHz~30MHz) close up photo















Report No.: EED32O81225001





Radiated emission Test Setup-3 (30MHz~1GHz)



Radiated emission Test Setup-4(30MHz~1GHz)close up photo















Report No.: EED32O81225001 Page 24 of 34



Radiated spurious emission Test Setup-5(Above 1GHz)



Radiated spurious emission Test Setup-6(Above 1GHz) There are absorbing materials under the ground.









