


Page 22 of 32 Report No.: EED32O80786301

APPENDIX 1 PHOTOGRAPHS OF TEST SETUP

Test Model No.: G3-3791200A-D1



Radiated emission Test Setup-1(9kHz~30MHz)



Radiated emission Test Setup-2 (30MHz~1GHz)














Report No.: EED32O80786301 Page 23 of 32



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz) There are absorbing materials under the ground.









