


Report No.: EED32O81225201 Page 22 of 36

## **APPENDIX 1 PHOTOGRAPHS OF TEST SETUP**

Test Model No.: S0-315



Radiated emission Test Setup-1(9kHz~30MHz)



Radiated emission Test Setup-2(9kHz~30MHz)close up photo














Report No.: EED32O81225201 Page 23 of 36



Radiated emission Test Setup-3 (30MHz~1GHz)



Radiated emission Test Setup-4 (30MHz $\sim$ 1GHz)close up photo






Report No.: EED32O81225201 Page 24 of 36



Radiated spurious emission Test Setup-5(Above 1GHz)



Radiated spurious emission Test Setup-6(Above 1GHz) There are absorbing materials under the ground.









