



Page 42 of 76 Report No.: EED32P80411701

6 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Below 1GHz) close up














Report No.: EED32P80411701







Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz) There are absorbing materials under the ground.













Report No.: EED32P80411701







Conducted Emissions Test Setup-1



Conducted Emissions Test Setup-2 (close up)









