

## Annex 3: External photographs 21-1-0120702T01a-A3

<b>Number of pages:</b>	7	<b>Date of Report:</b>	2022-Sep-20
<b>Testing company:</b>	CETECOM GmbH Im Teelbruch 116 45219 Essen Germany Tel. + 49 (0) 20 54 / 95 19-0 Fax: + 49 (0) 20 54 / 95 19-150	<b>Applicant:</b>	ARESIS srl
<b>Product:</b> <b>Model:</b>	Tank Level Probing Radar ScanBrick® W		
<b>FCC ID:</b>	2A7GA-SCANBRICKW	<b>IC:</b>	28648-SCANBRICKW
<b>Testing has been carried out in accordance with:</b>	<b>FCC Regulations</b> Title 47 CFR, Chapter I, Subchapter A, Part 15.31(q) <b>Subpart C Intentional Radiators</b> § 15.207 Conducted limits § 15.209 Radiated emission limits  <b>ISED-Regulations</b> <b>Radio Standards Specification</b> RSS-Gen, Issue 5 + A1 + A2 RSS-211, Issue 1 (March 2015) General Requirements for Compliance of Radio Apparatus  Deviations, modifications or clarifications (if any) to above mentioned documents are written in each section under "Test method and limit".		

## Table of Contents

1	External photographs of Main device under test (EUT/DUT) .....	3
	Photograph 1 : EUT 1_Front side view .....	3
	Photograph 2 : EUT 1_Rear side view .....	3
	Photograph 3 : EUT 1_Left side view .....	4
	Photograph 4 : EUT 1_Right side view .....	4
	Photograph 5 : EUT 1_Top side view .....	5
	Photograph 6 : EUT 1_Bottom side view .....	5
2	External photographs of Accessories .....	6
	Photograph 1 : AE 01 .....	6
	Photograph 2 : AE 02 - front .....	6
	Photograph 3 : AE2 - rear .....	7

## 1 External photographs of Main device under test (EUT/DUT)



Photograph 1: EUT 1\_Front side view



Photograph 2: EUT 1\_Rear side view



Photograph 3: EUT 1\_Left side view



Photograph 4: EUT 1\_Right side view



Photograph 5: EUT 1\_Top side view



Photograph 6: EUT 1\_Bottom side view

## 2 External photographs of Accessories



Photograph 1: AE 01



Photograph 2: AE 2 - front



Photograph 3: AE2 - rear

**End Of Annex 3**