




# **Appendix I - Photograph of test configuration**

**Report Number: MLT2311P15001**

## Conduction Test

### < Setup-F View >




**< Setup-R View>**



**Radiation Test (Below 1G)**  
**< RF Setup-F View>**



**< RF Setup-R View>**



# Radiation Test (Above 1G)

## < RF Setup-F View >



< RF Setup-R View>

