



Test Report	18070636
Page	5 of 8

EUT Internal Photo





Mainboard - Front View






Test Report	18070636
Page	6 of 8

Mainboard - Rear View



Battery - Front View






Test Report	18070636
Page	7 of 8

Battery - Rear View




LCD - Front View





Test Report	18070636
Page	8 of 8

LCD - Rear View



Antenna View

