












11N20SISO Ant1 2412 0-Reference




11N20SISO Ant1 2412 30-1000




11N20SISO Ant1 2412 1000-26500




11N20SISO Ant1 2437 0-Reference




11N20SISO Ant1 2437 30-1000




11N20SISO Ant1 2437 1000-26500




11N20SISO Ant1 2462 0-Reference




11N20SISO Ant1 2462 30-1000




11N20SISO Ant1 2462 1000-26500




11N40SISO Ant1 2422 0-Reference




11N40SISO Ant1 2422 30-1000




11N40SISO Ant1 2422 1000-26500




11N40SISO Ant1 2437 0-Reference




11N40SISO Ant1 2437 30-1000




11N40SISO Ant1 2437 1000-26500






APPENDIX A: PHOTOGRAPHS OF TEST SETUP



Radiated Spurious Emissions




Conducted Emissions at AC Power Line (150kHz-30MHz)



APPENDIX B: PHOTOGRAPHS OF EUT





----END OF REPORT----

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of BlueAsia, this report can't be reproduced except in full.