



Report No.: EED32N80943803 Page 83 of 85

9 PHOTOGRAPHS OF TEST SETUP

Test Model No.: OVO-K2



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32N80943803 Page 84 of 85



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



AC Power Line Conducted Emission













Report No. : EED32N80943803 Page 85 of 85

10 PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No.EED32N80943801 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

