

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AB5RHUB521
23-0085
June 27, 2023
SwipeSense, Inc.
Location Hub

INTERNAL PHOTOGRAPHS




Figure 1. EUT, Front Cover Removed

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AB5RHUB521
23-0085
June 27, 2023
SwipeSense, Inc.
Location Hub




Figure 2. Back of Main PCB

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AB5RHUB521
23-0085
June 27, 2023
SwipeSense, Inc.
Location Hub




Figure 3. Front of Main PCB

US Tech Test Report:
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification
2AB5RHUB521
23-0085
June 27, 2023
SwipeSense, Inc.
Location Hub




Figure 4. Enclosure with Main PCB Removed