



7 Test Setup Photo


Radiated Emission
Below 1GHz



Above 1GHz



Conducted Emission



8 EUT Constructional Details

Reference to the test report No. CCISE181210201

-----End of report-----