

Appendix 2 Photodocumentation


Division:
Industry & Energy

Description: Battery compartment opened

Test report reference:
2023-IN-AT-TICL-E-EX-
000018-FG-006

Page: 3 of 10

Date: 14.04.2023



Appendix 2 Photodocumentation


Division:
Industry & Energy

Description: Case opened

Test report reference:
2023-IN-AT-TICL-E-EX-
000018-FG-006

Page: 4 of 10

Date: 14.04.2023



Appendix 2 Photodocumentation


Division:
Industry & Energy

Description: Internal view #1

Test report reference:
2023-IN-AT-TICL-E-EX-
000018-FG-006

Page: 5 of 10

Date: 14.04.2023



Appendix 2 Photodocumentation


Description: Internal view #2

Division:
Industry & Energy

Test report reference:
2023-IN-AT-TICL-E-EX-
000018-FG-006

Page: 6 of 10

Date: 14.04.2023



Appendix 2

Photodocumentation

Division:
Industry & Energy

Description: Internal view #3

Test report reference:
2023-IN-AT-TICL-E-EX-
000018-FG-006

Page: 7 of 10

Date: 14.04.2023

