

## Appendix 2 Photodocumentation


**Division:**  
Industry & Energy

Description: exploded view

Test report reference:  
2023-IN-AT-TICL-E-EX-0-  
000018-FG-034

Page: 3 of 11

Date: 22.11.2023



## Appendix 2 Photodocumentation


**Division:**  
Industry & Energy

Description: exploded view, battery compartment removed

Test report reference:  
2023-IN-AT-TICL-E-EX-0-  
000018-FG-034

Page: 4 of 11

Date: 22.11.2023



## Appendix 2 Photodocumentation


**Division:**  
Industry & Energy

Description: PCB view #1

Test report reference:  
2023-IN-AT-TICL-E-EX-0-  
000018-FG-034

Page: 5 of 11

Date: 22.11.2023



## Appendix 2 Photodocumentation

Division:  
Industry & Energy

Description: PVB view #2

Test report reference:  
2023-IN-AT-TICL-E-EX-0-  
000018-FG-034

Page: 6 of 11

Date: 22.11.2023



## Appendix 2 Photodocumentation


**Division:**  
Industry & Energy

Description: Antenna closeup #1, dimensions in centimeter

Test report reference:  
2023-IN-AT-TICL-E-EX-0-  
000018-FG-034

Page: 7 of 11

Date: 22.11.2023



## Appendix 2 Photodocumentation

**Division:**  
Industry & Energy

Description: Antenna closeup #2, dimensions in centimeter

Test report reference:  
2023-IN-AT-TICL-E-EX-0-  
000018-FG-034

Page: 8 of 11

Date: 22.11.2023

