


Test Report No.:  
Prüfbericht - Nr.:


<Photographs of EUT>



Test Report No.:  
Prüfbericht - Nr.:

<Antenna Location>

EUT Top Side



EUT Bottom Side  
<EUT Front View>

<Photographs of SAR Setup>



Front Face of EUT with 0.5 cm Gap




Rear Face of EUT with 0.5 cm Gap



Left Side of EUT with 0.5 cm Gap



Right Side of EUT with 0.5 cm Gap



Top Side of EUT with 0.5 cm Gap



Bottom Side of EUT with 0.5 cm Gap