









PHOTOGRAPHS OF TEST SETUP

Test model No.: SC10202



Radiated spurious emission Test Setup-1(Below 30MHz)
















Report No. :EED32M80075901

Page 102 of 115



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz)
There are absorbing materials under the ground.






















Conducted Emissions Test Setup





















































