


Photographs –Model TURBO DG2014 Test Setup

Photograph – Conducted Emission Test Setup at Test Site 2#




Photograph – Radiation Spurious Emission Test Setup


32.768kHz ~30MHz at Test Site 2#




30MHz-1GHz at Test Site 2#



Above 1GHz at Test Site 1#



Photograph – Extreme Condition Test Setup



Photograph – 2G&3G Conducted Test Setup

