


Photographs –Model LEO DG280 Test Setup

Photograph – Conducted Emission Test Setup at Test Site 1#




Photograph – Radiation Spurious Emission Test Setup

32.768kHz ~30MHz at Test Site 2#



30MHz-1GHz at Test Site 2#



Above 1GHz at Test Site 1#



Photograph – Extreme Condition Test Setup



Photograph –2G&3G Conducted Test Setup

