





## PHOTOGRAPHS OF TEST SETUP

Test model No.:ER1



Radiated spurious emission Test Setup-1(Below 30MHz)



Radiated spurious emission Test Setup-2(Below 1GHz)














Report No. : EED32M00166301 Page 47 of 57



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup
There are absorbing materials under the ground.













Report No.: EED32M00166301







**Conducted Emissions Test Setup** 











