

Report No.: EED32M00324201






PHOTOGRAPHS OF TEST SETUP

Test model No.: PO6



Radiated spurious emission Test Setup-2(Below 30MHz)



Radiated spurious emission Test Setup-1(Below 1GHz)














Report No.: EED32M00324201





Radiated spurious emission Test Setup-2(Above 1GHz)



Radiated spurious emission Test Setup-3(Above 1GHz)
There are absorbing materials under the ground.









