Report No.: EED32O80001001 Page 28 of 42

9 PHOTOGRAPHS OF TEST SETUP

Test model No.: BP2V



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)

Report No. : EED32O80001001 Page 29 of 42



Radiated spurious emission Test Setup-3(Above 1GHz)
There are absorbing materials under the ground.