



# Photos

---

## Radio parameter test of main terminal according to FCC and IC specification

Performed for JE electronic a/s

Page 1 of 7

This exhibit is an extract of

DELTA Test Report T220089-2 DANAK-19/15444  
dated 09 July 2015

containing only the photos of the test setups

**DELTA**  
Venlighedsvej 4  
2970 Hørsholm  
Denmark

Tel. +45 72 19 40 00  
Fax +45 72 19 40 01  
[www.delta.dk](http://www.delta.dk)  
VAT No. 12275110



Photo 4.1.1 Test setup regarding measurement of radiated emission.



Photo 4.1.2 Test setup regarding measurement of radiated emission.



Photo 4.1.3 Test setup regarding measurement of radiated emission.



Photo.4.1.4 Test setup regarding measurement of radiated emission.





Photo 4.2.1 Test setup regarding measurement of field strength of fundamental.



Photo 4.2.2 Test setup regarding measurement of field strength of fundamental.




Photo 4.3.1 Test setup regarding measurement of band edge compliance.



Photo 4.3.2 Test setup regarding measurement of band edge compliance.





Photo 4.4.1 Test setup regarding measurement of 20 dB bandwidth.




Photo 4.4.2 Test setup regarding measurement of 20 dB bandwidth.





Photo 4.5.1 Test setup regarding measurement of occupied bandwidth, IC.




Photo 4.5.2 Test setup regarding measurement of occupied bandwidth, IC.