

Test report No. : 4788934758-EP

Page : 1 of 108

Issued date : August 6, 2019

# **Product Photos**

**External Photos** 





Test report No. : 4788934758-EP Page : 2 of 108

Issued date : August 6, 2019

**Model: MiiS Horus Scope DSC 300P** 





#### **Underwriters Laboratories Taiwan Co., Ltd.**



Test report No. : 4788934758-EP

Page : 3 of 108

Issued date : August 6, 2019





#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP

Page : 4 of 108

Issued date : August 6, 2019







Test report No. : 4788934758-EP Page : 5 of 108

Page : 5 of 108 Issued date : August 6, 2019





#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP

Page : 6 of 108

Issued date : August 6, 2019





#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 7 of 108

Issued date : August 6, 2019

# Model No. of Lens: MiiS Horus Scope Adapter 300





#### **Underwriters Laboratories Taiwan Co., Ltd.**



Test report No. : 4788934758-EP

Page : 8 of 108

Issued date : August 6, 2019





#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 9 of 108

Issued date : August 6, 2019

### Model No. of Lens: MiiS Horus Scope DDC 100






#### **Underwriters Laboratories Taiwan Co., Ltd.**



Test report No. : 4788934758-EP Page : 10 of 108 Issued date : August 6, 2019





#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 11 of 108 Issued date : August 6, 2019





### Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 12 of 108 Issued date : August 6, 2019

Model No. of Lens: MiiS Horus Scope DDC 200





#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 13 of 108 Issued date : August 6, 2019





#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 14 of 108 Issued date : August 6, 2019





#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 15 of 108 Issued date : August 6, 2019





Test report No. : 4788934758-EP Page : 16 of 108

Issued date : August 6, 2019

# Model No. of Lens: MiiS Horus Scope DEA 100






#### **Underwriters Laboratories Taiwan Co., Ltd.**



Test report No. : 4788934758-EP Page : 17 of 108

Issued date : August 6, 2019





#### **Underwriters Laboratories Taiwan Co., Ltd.**



Test report No. : 4788934758-EP Page : 18 of 108 Issued date : August 6, 2019



#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 19 of 108

Issued date : August 6, 2019

### Model No. of Lens: MiiS Horus Scope DEA 200P





#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 20 of 108 Issued date : August 6, 2019





#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 21 of 108 Issued date : August 6, 2019





#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 22 of 108 Issued date : August 6, 2019





#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 23 of 108 Issued date : August 6, 2019





#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 24 of 108 Issued date : August 6, 2019





#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 25 of 108 Issued date : August 6, 2019





#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 26 of 108 Issued date : August 6, 2019





Test report No. : 4788934758-EP Page : 27 of 108

Issued date : August 6, 2019

# Model No. of Lens: MiiS Horus Scope DEC 100






#### **Underwriters Laboratories Taiwan Co., Ltd.**



Test report No. : 4788934758-EP Page : 28 of 108 Issued date : August 6, 2019





#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 29 of 108 Issued date : August 6, 2019





#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 30 of 108 Issued date : August 6, 2019





Test report No. : 4788934758-EP Page : 31 of 108 Issued date : August 6, 2019

# Model No. of Lens: MiiS Horus Scope DGC 100






#### **Underwriters Laboratories Taiwan Co., Ltd.**



Test report No. : 4788934758-EP Page : 32 of 108 Issued date : August 6, 2019





#### **Underwriters Laboratories Taiwan Co., Ltd.**



Test report No. : 4788934758-EP Page : 33 of 108 Issued date : August 6, 2019



#### **Underwriters Laboratories Taiwan Co., Ltd.**



Test report No. : 4788934758-EP Page : 34 of 108 Issued date : August 6, 2019

### **Model No. of Lens: MiiS Horus Scope DOC 100S**





#### **Underwriters Laboratories Taiwan Co., Ltd.**



Test report No. : 4788934758-EP Page : 35 of 108 Issued date : August 6, 2019





#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 36 of 108 Issued date : August 6, 2019





#### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 37 of 108 Issued date : August 6, 2019





Test report No. : 4788934758-EP Page : 38 of 108 Issued date : August 6, 2019

### Model No. of Lens: MiiS Horus Scope DOC 300S





### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 39 of 108 Issued date : August 6, 2019





### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 40 of 108 Issued date : August 6, 2019





### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 41 of 108

Issued date : August 6, 2019

## Model No. of Lens: MiiS Horus Scope EEC 100






### **Underwriters Laboratories Taiwan Co., Ltd.**



Test report No. : 4788934758-EP Page : 42 of 108 Issued date : August 6, 2019





### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 43 of 108 Issued date : August 6, 2019





### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 44 of 108 Issued date : August 6, 2019






Test report No. : 4788934758-EP Page : 45 of 108

Page : 45 of 108 Issued date : August 6, 2019


### **Charging Station DSC 300**








Test report No. : 4788934758-EP Page : 46 of 108 Issued date : August 6, 2019






### **Underwriters Laboratories Taiwan Co., Ltd.**



Test report No. : 4788934758-EP Page : 47 of 108 Issued date : August 6, 2019






### Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 48 of 108

Issued date : August 6, 2019





### Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 49 of 108

Issued date : August 6, 2019





### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 50 of 108

Issued date : August 6, 2019

### **ILS 100**





### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 51 of 108 Issued date : August 6, 2019





### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 52 of 108 Issued date : August 6, 2019





### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 53 of 108 Issued date : August 6, 2019




### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 54 of 108 Issued date : August 6, 2019





### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 55 of 108

Issued date : August 6, 2019





### **Underwriters Laboratories Taiwan Co., Ltd.**



Test report No. : 4788934758-EP Page : 56 of 108 Issued date : August 6, 2019





### **Underwriters Laboratories Taiwan Co., Ltd.**



Test report No. : 4788934758-EP Page : 57 of 108 Issued date : August 6, 2019






### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 58 of 108 Issued date : August 6, 2019





### **Underwriters Laboratories Taiwan Co., Ltd.**



Test report No. : 4788934758-EP Page : 59 of 108 Issued date : August 6, 2019





### Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan Telephone :+886-2-7737-3000



Test report No. : 4788934758-EP Page : 60 of 108 Issued date : August 6, 2019





### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page Issued date : 61 of 108 : August 6, 2019





## Underwriters Laboratories Taiwan Co., Ltd.


Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan Telephone :+886-2-7737-3000
Facsimile (FAX ) :+886-3-583-7948



Test report No. : 4788934758-EP Page : 62 of 108

Issued date : August 6, 2019

### **CR-100**






### Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 63 of 108 Issued date : August 6, 2019





### Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 64 of 108

Issued date : August 6, 2019





### Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan Telephone :+886-2-7737-3000



Test report No. : 4788934758-EP Page : 65 of 108

Issued date : August 6, 2019




Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 66 of 108 Issued date : August 6, 2019

# Slit lamp jig







### **Underwriters Laboratories Taiwan Co., Ltd.**



Test report No. : 4788934758-EP Page : 67 of 108 Issued date : August 6, 2019

### **Memory Card**







Test report No. : 4788934758-EP Page : 68 of 108 Issued date : August 6, 2019

### **Battery**





### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 69 of 108 Issued date : August 6, 2019





### **Underwriters Laboratories Taiwan Co., Ltd.**



Test report No. : 4788934758-EP Page : 70 of 108 Issued date : August 6, 2019

### **Power Adapter**





### **Underwriters Laboratories Taiwan Co., Ltd.**



Test report No. : 4788934758-EP Page : 71 of 108 Issued date : August 6, 2019





### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 72 of 108 Issued date : August 6, 2019

## **AU Plug**





### Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 73 of 108

Issued date : August 6, 2019

## **EU Plug**





### **Underwriters Laboratories Taiwan Co., Ltd.**



Test report No. : 4788934758-EP Page : 74 of 108 Issued date : August 6, 2019

# **UK Plug**





### Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 75 of 108 Issued date : August 6, 2019

# **US Plug**





### Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan Telephone :+886-2-7737-3000



Test report No. : 4788934758-EP Page : 76 of 108

Issued date : August 6, 2019

### **HDMI Cable**





### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page Issued date : 77 of 108 : August 6, 2019



Facsimile (FAX ) :+886-3-583-7948



Test report No. : 4788934758-EP Page : 78 of 108

Issued date : August 6, 2019

### **USB Cable**





### **Underwriters Laboratories Taiwan Co., Ltd.**

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page Issued date : 79 of 108 : August 6, 2019



Facsimile (FAX ) :+886-3-583-7948