

Test report No. : 4788934758-EP Page : 80 of 108

Issued date : August 6, 2019

Internal Photos

Model: MiiS Horus Scope DSC 300P





Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 81 of 108 Issued date : August 6, 2019





Underwriters Laboratories Taiwan Co., Ltd.


Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 82 of 108

Issued date : August 6, 2019






Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 83 of 108

Issued date : August 6, 2019






Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 84 of 108

Issued date : August 6, 2019







Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 85 of 108 Issued date : August 6, 2019







Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 86 of 108 Issued date : August 6, 2019






Underwriters Laboratories Taiwan Co., Ltd.


Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 87 of 108

Issued date : August 6, 2019






Underwriters Laboratories Taiwan Co., Ltd.



Test report No. : 4788934758-EP Page : 88 of 108 Issued date : August 6, 2019







Underwriters Laboratories Taiwan Co., Ltd.



Test report No. : 4788934758-EP Page : 89 of 108 Issued date : August 6, 2019







Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 90 of 108 Issued date : August 6, 2019







Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 91 of 108 Issued date : August 6, 2019







Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 92 of 108 Issued date : August 6, 2019







Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 93 of 108 Issued date : August 6, 2019







Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 94 of 108 Issued date : August 6, 2019





Underwriters Laboratories Taiwan Co., Ltd.


Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 95 of 108

Issued date : August 6, 2019







Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 96 of 108 Issued date : August 6, 2019






Underwriters Laboratories Taiwan Co., Ltd.



Test report No. : 4788934758-EP Page : 97 of 108

Issued date : August 6, 2019





Underwriters Laboratories Taiwan Co., Ltd.


Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 98 of 108

Issued date : August 6, 2019






Underwriters Laboratories Taiwan Co., Ltd.


Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 99 of 108

Issued date : August 6, 2019







Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 100 of 108 Issued date : August 6, 2019






Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 101 of 108 Issued date : August 6, 2019







Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 102 of 108 Issued date : August 6, 2019







Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 103 of 108 Issued date : August 6, 2019






Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 104 of 108 Issued date : August 6, 2019







Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 105 of 108 Issued date : August 6, 2019







Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 106 of 108 Issued date : August 6, 2019







Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 107 of 108 Issued date : August 6, 2019





Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan



Test report No. : 4788934758-EP Page : 108 of 108 Issued date : August 6, 2019

