

Project #234111406
Report Date: 12/10/20

Report # 31964658.001

EUT Internal Photos



Figure 1 - Internal Photo of EUT- Cover off View




Figure 2 - Internal Photo of EUT- Top View




Figure 3 - Internal Photo of EUT- Bottom View




Figure 4 - Internal Photo of EUT- Antenna Location View