


Report No. : EED32N80972801



Page 39 of 51

7 PHOTOGRAPHS OF TEST SETUP

Test model No.:VA-IH006





Report No. : EED32N80972801



Page 40 of 51



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



Conducted Emissions Test Setup

