
EUT TEST PHOTOGRAPHS

Photograph of the depth in the Head Phantom




Photograph of the depth in the Body Phantom



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 1 of 6



Head Setup Photo(Left Tilt)




This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 2 of 6


SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD.Report

No.: LCS1603292459E


Head Setup Photo(Right Cheek)



Head Setup Photo(Right Tilt)




This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 3 of 6



10mm body-worn Back Side Setup Photo(hotspot)

10mm body-worn Front Side Setup Photo(hotspot)



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 4 of 6



10mm body-worn Right Side Setup Photo(hotspot)

10mm body-worn Left Side Setup Photo(hotspot)



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 5 of 6



10mm body-worn Top Side Setup Photo(hotspot)

10mm body-worn Bottom Side Setup Photo(hotspot)



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 6 of 6