

1 EUT Internal Photos




Photo 1: EUT Top Panel removed



Photo 2: EUT Bottom Panel removed

Prüfbericht - Nr.:
Test Report No.:

19660367 001
19660368 001

Seite 2 von 4
Page 2 of 4




Photo 3: PCB front view




Photo 4: PCB rear view




Photo 5: RF Module with shield




Photo 6: RF Module with shielding removed

Prüfbericht - Nr.:
Test Report No.:

19660367 001
19660368 001

Seite 4 von 4
Page 4 of 4




Photo 7: EUT Battery 1



Photo 8: EUT Battery 2

*****END OF APPENDIX*****