








Report No.: EED32L00396101

400


## (21)

## PHOTOGRAPHS OF TEST SETUP

Test Model No.: YTXJ03FM



Radiated spurious emission Test Setup-1(Below 30MHz)



Radiated spurious emission Test Setup-2(Below 1GHz)














Report No. : EED32L00396101 Page 103 of 113



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz)
There are absorbing materials under the ground.




















Report No.: EED32L00396101











**Conducted Emissions Test Setup** 





















































