



Report No.: EED32M00298803



PHOTOGRAPHS OF TEST SETUP

Test model No.:GemiBook










Report No.: EED32M00298803





Radiated spurious emission Test Setup-2(Above 1GHz)



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.













Report No.: EED32M00298803
































































PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No. EED32M00298801 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.



Hotline: 400-6788-333 www.cti-cert.com E-mail: info@cti-cert.com Complaint call: 0755-33681700 Complaint E-mail: complaint@cti-cert.com