







Report No.: EED32M00298804

PHOTOGRAPHS OF TEST SETUP

Test model No.:GemiBook

















































Radiated spurious emission Test Setup-2(Above 1GHz)



Radiated spurious emission Test Setup-3(Above 1GHz)
There are absorbing materials under the ground.














Report No. : EED32M00298804 Page 102 of 103



Radiated spurious emission Test Setup-4(Above 18GHz)



Conducted Emissions Test Setup



















Report No.: EED32M00298804

PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No.EED32M00298801 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

*** End of Report ***

