



Report No. : EED32M00265502 Page 49 of 52

PHOTOGRAPHS OF TEST SETUP

Test model No.:HeroBox



Radiated spurious emission Test Setup-1(Below 30MHz)



Radiated spurious emission Test Setup-2(Below 1GHz)














Report No.: EED32M00265502 Page 50 of 52



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz)
There are absorbing materials under the ground.





















Conducted Emissions Test Setup















Report No. : EED32M00265502



Page 52 of 52

PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No. EED32M00265501 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

