


Test report	FCC_IC_RF_SL17032201-SEV-019_Co-Location
Page	10 of 24

6.6 EUT Test Setup Photos



Radiated Emissions (<30MHz) - Front View

Radiated Emissions (<30MHz) - Rear View





Radiated Emissions (<1GHz) - Front View

Radiated Emissions (<1GHz) - Rear View





Radiated Emissions (>1GHz) – Front View

Radiated Emissions (>1GHz) - Rear View