


Report No.: EED32O81825501


Page 45 of 53

7 PHOTOGRAPHS OF TEST SETUP

Test Model No.: AESEM1S



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)













Report No.: EED32O81825501

