

3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 14057, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Report No.: KES-E1-19T0746 Page (21) of (25)

APPENDIX B - Test Setup Photos and Configuration

Conducted Voltage Emissions

■ Charge Mode








3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 14057, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Report No.: KES-E1-19T0746 Page (22) of (25)

Radiated Electric Field Emissions(Below 1 6 ₪)

■ Operation Mode








3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 14057, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Report No.: KES-E1-19T0746 Page (23) of (25)

■ Charge Mode








3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 14057, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Report No.: KES-E1-19T0746 Page (24) of (25)

Radiated Electric Field Emissions(Above 1 6 ₪)

■ Operation Mode







3701, 40, Simin-daero 365beon-gil, Dongan-gu, Anyang-si, Gyeonggi-do, 14057, Korea Tel: +82-31-425-6200 / Fax: +82-31-424-0450 www.kes.co.kr Report No.: KES-E1-19T0746 Page (25) of (25)

■ Charge Mode

