The Worst Case Configuration Photographs

Radiated Emission




Front View



Rear View

The Worst Case Configuration Photographs

Radiated Emission





Rear View

The Worst Case Configuration Photographs

Radiated Emission




Front View



Rear View

The Worst Case Configuration Photographs

Radiated Emission



Front View



Rear View

Test Report Number: 17062193HKG-001

FCC ID: 2AJ9OSFG8000B2

The Worst Case Configuration Photographs

AC Conducted Emission




Front View



Side View 1

The Worst Case Configuration Photographs

AC Conducted Emission



Side View 2

The Worst Case Configuration Photographs

AC Conducted Emission



Front View



Side View 1

The Worst Case Configuration Photographs

AC Conducted Emission



Side View 2