



# ANNEX A TEST SETUP PHOTOS

### <u>PHOTO 1</u>

Photo of Power Line Conducted Emission Test



Report No.: 8231EU010202W-AA

### PHOTO 2

Photo of Radiated Emission Test (Below 1GHz) Left Ear




#### SHENZHEN EU TESTING LABORATORY LIMITED



Page 2 of 2 Report No.: 8231EU010202W-AA

## **PHOTO 3**

Photo of Radiated Emission Test (Above 1GHz) Left Ear



--- End ---