


Report No.: EED32O81145101

Page 33 of 43

7 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)













Report No.: EED32O81145101







Radiated spurious emission Test Setup-3(Above 1GHz)
There are absorbing materials under the ground.











































