
APPENDIX 3: Photographs of Test Setup

Transmitter unwanted emissions (X Axis)



Photo 1



Photo 2

Transmitter unwanted emissions (Y Axis)



Photo 1




Photo 2

Transmitter unwanted emissions (Z Axis)



Photo 1




Photo 2

Worst Case Position

		614.100 MHz to 615.900 MHz	657.100 MHz to 662.900 MHz
Below 1 GHz	Horizontal	X	X
	Vertical	X	X
Above 1 GHz	Horizontal	Y	X
	Vertical	Z	X

X-axis



Y-axis



Z-axis



Antenna Terminal Tests




Photo 1

End of Report