

INTERTEK TESTING SERVICES


The Worst Case Configuration Photographs



Radiated Emission – Dongle Unit



Rear View



INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

AC Conducted Emission - Dongle Unit



Front View



Side View 1

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

AC Conducted Emission – Dongle Unit



Side View 2