



8 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1 Left ear (Below 1GHz)



Radiated spurious emission Test Setup-2 Left ear (Below 1GHz) close up














Report No.: EED32P81818401 Page 44 of 68



Radiated spurious emission Test Setup-3 Left ear(Above 1GHz)



Radiated spurious emission Test Setup-4 Right ear(Below 1GHz)














Report No.: EED32P81818401 Page 45 of 68



Radiated spurious emission Test Setup-5 Right ear(Below 1GHz) close up



Radiated spurious emission Test Setup-6 Right ear(Above 1GHz)














Page 46 of 68 Report No.: EED32P81818401



Radiated spurious emission Test Setup-7 (Above 1GHz) There are absorbing materials under the ground.



Conducted Emissions Test Setup-1



















Conducted Emissions Test Setup-2 (close up)



Conducted Emissions Test Setup-3 (close up)



Page 47 of 68