

Report No.: EED32P80288201

Page 49 of 72

8 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Below 1GHz Close up)















Report No.: EED32P80288201







Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz) There are absorbing materials under the ground.













Report No.: EED32P80288201

