
APPENDIX 3: Photographs of Test Setup

Conducted Emission




Photo 1




Photo 2

Radiated Spurious Emission




Photo 1




Photo 2

Worst Case Position

Below 1 GHz (Horizontal: Z-axis / Vertical: Z-axis)
Above 1 GHz (Horizontal: X-axis / Vertical: Y-axis)


X-axis



Y-axis



Z-axis



Worst Case Confirmation



With Metal frame



Without Metal frame (Worst)

Antenna Terminal Conducted Tests



Photo 1



Photo 2

End of Report