


Report No.: EED32N80617801


## Page 48 of 58

## **8 PHOTOGRAPHS OF TEST SETUP**

Test Model No.: MW-JS1



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)













Report No.: EED32N80617801





**Conducted Emissions Test Setup** 



There are absorbing materials under the ground









