


Report No. : EED32L00157501 Page 108 of 113

## PHOTOGRAPHS OF TEST SETUP

Test model No.: MSS620



Radiated spurious emission Test Setup-1(Below 30MHz)



Radiated spurious emission Test Setup-2(Below 1GHz)














Report No. : EED32L00157501 Page 109 of 113



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz)

There is absorber on the ground floor







































**Conducted Emissions Test Setup** 













































