

Page 1 of 13

Report Ref. No: 181201727SHA-001

Photo 1

Description: overall view




Photo 2

Description: overall view







Page 2 of 13

Report Ref. No: 181201727SHA-001



Description: internal view




Photo 4

Description: main body and dust container







Page 3 of 13

Report Ref. No: 181201727SHA-001

Photo 5

Description: bottom view





Photo 6

Description: bottom view







Page 4 of 13

Report Ref. No: 181201727SHA-001

Photo 7


Description: internal view



Photo 8

Description: internal view of DS3G, DS3G.\*\*





Intertek Testing Services Shanghai
Building No.86, 1198 Qinzhou Road (North), Shanghai 200233, China
Tel: 86 21 6127 8200 Fax: 86 21 5426 2346 www.intertek.com



Page 5 of 13

Report Ref. No: 181201727SHA-001







Photo 10






















Page 6 of 13

Report Ref. No: 181201727SHA-001



Description: internal view




Photo 12




















Page 7 of 13

Report Ref. No: 181201727SHA-001






Photo 14









Page 8 of 13


Report Ref. No: 181201727SHA-001

Photo 15



Photo 16









Page 9 of 13


Report Ref. No: 181201727SHA-001

Photo 17

Description: internal view



Photo 18









Page 10 of 13

Report Ref. No: 181201727SHA-001






Photo 20













Page 11 of 13

Report Ref. No: 181201727SHA-001








Photo 22









Page 12 of 13

Report Ref. No: 181201727SHA-001

## Photo 23





Photo 24









Page 13 of 13

Report Ref. No: 181201727SHA-001



Description: charging station



Photo 26





